

Cracks in garboard at stem area

